Ref	Hits	Search Ouen	DBs	Default	Plurals	Time Stamp
#	ПІС	Search Query	DOS	Operator	Plurais	Time Stamp
L1	12391	(calibrat\$ or adjust\$ or zero\$) near7 (flowmeter\$ or ((flow or volum\$) near4 (sensor\$ or detector\$ or meter\$)))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2005/08/21 12:46
L2	1712	coriolis near5 (flowmeter\$ or ((flow or volume\$) near3 (sensor\$ or detector\$ or meter\$)))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2005/08/21 12:46
L4	398	(vibrate or vibrating or vibrated or vibrates) near7 (tube or tubes or conduit or conduits or pipe or pipes) near5 (flowmeter or flowmeters or ((flow or volume\$) near3 (sensor\$ or detector\$ or meter\$)))	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2005/08/21 12:48
L5	82	(determin\$ or comput\$ or calculat\$) near7 zero near10 (correction or calibrat\$) near7 (coefficient or factor or value) near19 (stored or previous\$) near7 zero\$	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2005/08/21 12:50
L6	0	2 and 4 and 5	US-PGPUB; USPAT; EPO; JPO; DERWENT	OR	OFF	2005/08/21 12:50